

Maintenance Manual

General cleaning and maintenance of melamine boards

Any adhesive material that may remain after installation can be removed with an adhesive solvent. It is not recommended to frequently use solvents to clean the panels. Laminate panels can be cleaned with water and soap using a non-abrasive cloth. Coffee, tea or other type of difficult stains can be removed using a mild soap. It is important not to rub the surfaces more than 10 or 20 times, as this can damage the finishes. It is important not to use chemicals or abrasive cleaners. If the panel finish comes in contact with this type of product, clean and dry immediately. Brushes or abrasive pads can scratch the finish or cause some of its shine to disappear, while encouraging the appearance of new stains. The panel finish can also be damaged if sharp objects are used directly on it.

General cleaning and maintenance of glass surfaces

It is recommended not to use blades or knives on all glass surfaces, as this can cause permanent damage. When paint or other building materials cannot be cleaned on

glass surfaces with soap and water, use a razor blade. Razor blades can only be used on small surfaces and must always be used in one direction. Never use a razor blade in a back and forth manner, it could scratch the glass permanently.

General cleaning and maintenance of anodised aluminum

Use a brush or sponge with water. If stains remain, use a mild detergent in water with a soft brush or sponge. Clean in a horizontal motion first, then with a vertical movement.

To do

Clean the windows by always starting at the top and going down. Clean glass surfaces with soap and water regularly. Use a non-abrasive cleaner for the glass. Use a squeegee to remove the mixture of water and soap. Dry the joints and frames of any cleaning fluid.

Not to do

Clean the tinted glass under a radiant sun.
Leave dirt and dust on the glass surfaces for long period.

Touch glass surfaces with the metal parts of the cleaning instruments. Allow abrasive particles to lodge between the cloth and the glass surface.

Important to know

If a glass surface is slightly scratched, it can sometimes be repaired with a cerium oxide product.

Recommended cleaning agents:

Windex (or equivalent) for commercial use to clean glass or car polish to clean anodized aluminum